

Welding & Cutting



DO

- ✓ Personal protective gear must be used according to the type of work.
- ✓ The safety gear must be checked before use (Israeli standard, validity and correctness).
- ✓ The work area must be demarcated and ventilated according to the environmental risks.
- ✓ Combustible materials and waste must be removed from the work area.
- ✓ Make sure firefighting equipment is available, suitable and in working condition.
- ✓ The welding equipment must be protected from damage during work.
- ✓ Work with hazardous materials according to their work instructions.
- ✓ Hazardous materials must be stored in accordance with their storage instructions.
- ✓ You must act in accordance with the hot work procedure.
- ✓ Ensure the presence of first aid equipment.
- ✓ Hands should be washed with soap and water after work.



DON'T

- ✗ Do not perform welding/cutting work without personal protective gear and without knowing the risks.
- ✗ Do not perform cutting/welding work without proper training.
- ✗ Do not touch the welded parts, before they have cooled, without appropriate personal protective gear.
- ✗ Do not start any work before all combustible materials and risk factors have been removed.
- ✗ Do not wrap the welding cable around the body or shoulder.
- ✗ Do not allow pedestrians and vehicle traffic in the work environment.
- ✗ Do not perform cutting/welding operations in spaces without ventilation and without suitable suction systems.
- ✗ Do not leave the work area before the heat sources have completely cooled down.
- ✗ Eating and drinking are prohibited in the work environment.

